


OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office

567 E. Hudson St.
Columbus, OH 43211
614/298-2000



1. No. BUT233711		2. County Butler		4. Present Name(s) Pumphrey Milk House		1. No. BUT233711
3. Location of Negatives Ohio Historic Preservation Office				5. Historic or Other Name(s) Henry Robinson Milk House		
Roll No.		Picture No.(s)				
6. Specific Address or Location 3601 Hamilton-New London Rd				16. Thematic Associations: AGRICULTURE Dairy Farm		2. County Butler
				28. No. of Stories One story		
6a. Lot, Section or VMD Number Section 30				17. Date(s) or Period c. 1915		29. Basement? No
7. City or Village Ross (Township of)				17b. Alteration Date(s)		30. Foundation Material Concrete slab
8. Site Plan with North Arrow 				18. Style Class and Design No academic style - Vernacular		31. Wall Construction Tile block/hollow tile
9. U.T.M. Reference Quadrangle Name: Shandon				18a. Style Class and Design of Addition or Elements(s)		4. Present or Historic Name(s) Henry Robinson Milk House
16 698725 4355530 Zone Easting Northing				19. Architect or Engineer		
10. Classification: Building				19a. Design Sources		32. Roof Type: Gable
11. On National Register? No				20. Contractor or Builder		Roof Material: Metal
13. Part of Established Hist. Dist? No				21. Building Type or Plan		33. No. of Bays: 1 Side Bays: 1
15. Other Designation or District Name (NR or Local)				22. Original Use, if apparent Agricultural Outbuildings		34. Exterior Wall Material(s) Tile block
				23. Present Use STORAGE		35. Plan Shape Rectangular
				24. Ownership Private		36. Changes associated with 17/17b Dates: 17. 17b.
				25. Owner's Name & Address, if known John & Virginia Pumphrey 125 Pebble Ridge Lane Cresson, TX		37. Window Type(s)
				26. Property Acreage 240		38. Building Dimensions
				27. Other Surveys		39. Endangered? No By What?
						40. Chimney Placement No chimney observed
						41. Distance from & Frontage on Road
42. Further Description of Important Interior and Exterior Features (Continued on Reverse if Necessary) Located immediately north of the barn, the milk house is a ca. 1915 single room, one story gable-roofed structure constructed of glazed brown, vermiculated tile. A single door marks the south gable end facing the barn. The corrugated metal roof is a recent installation. The interior featured a concrete trough that when filled with spring water kept the milk cans cool. During the 1950s the Board of Health closed the milkhouse and a new electric powered milk cooler was built on the barn's west continued...						6. Specific Address or Location 3601 Hamilton-New London Rd
43. History and Significance (Continue on Reverse if necessary) The milk house was probably built in the early 20th century by Henry and Alice Robinson. Around 1900 they acquired the farm along with Charles Robinson and converted it to a Jersey dairy operation.						
44. Description of Environment and Outbuildings (See #52) The milk house is located on the historic Halstead - Scott-Robinson farm. The Scott Barn [BUT-2331-11] and the Scott Granary [BUT-2332-11] are south of the milk house.						
45. Sources of Information Virginia Robinson Pumphrey; Williams, Stephen. The Saga of Paddy's Run. 1945						

1. No. BUT233711	2. County Butler	4. Present Name(s)	I. No. BUT233711
3. Location of Negatives Ohio Historic Preservation Office		Pumphrey Milk House	
Roll No.	Picture No.(s)	5. Historic or Other Name(s) Henry Robinson Milk House	

51. Condition of Property: **Good/Fair**

52. Historic Outbuildings and Dependencies

	<u>Date</u>	<u>Associated Activity</u>
Other Barn		

53. Affiliated Site Numbers:

<u>Historic (OHD)</u>	<u>Archaeological (OAI)</u>
BUT233111	BU0085
BUT233211	

Door Selection: **Single off center**

Door Position:

Orientation: **Gable end axis**

Symmetry: **Bilateral asymmetry**

FOR OHPO USE ONLY:


49. Revised By:

50a. Date Revised:

50b. Reviewed by:

RPR Number:

54. Farmstead Plan



42. Further Description of Important Interior and Exterior Features (Con't)
elevation. This addition was removed in the 1990s.

43. History and Significance (Con't)

44. Description of Environment and Outbuildings (Con't)

45. Sources (Con't)

1. No. **BUT233711** | 2. County **Butler**

4. Present Name(s)

I. No.
BUT233711

3. Location of Negatives
Ohio Historic Preservation Office

Pumphrey Milk House

Roll No. | Picture No.(s)

5. Historic or Other Name(s)

Henry Robinson Milk House

