


CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

OHIO HISTORIC INVENTORY

1. No. 11 BUT-55-8		4. Present Name(s) AMERICAN LEGION, MIDDLETOWN POST # 218	
2. County BUTLER		5. Other Name(s) CAPT. ROBERT WILSON HOUSE	
3. Location of Negatives CITY OF MIDDLETOWN			
3. Specific Location 116 S. MAIN STREET (LOT 57, PARCEL 20, WARD)		16. Thematic Category	
7. City or Town If Rural, Township & Vicinity MIDDLETOWN, OHIO		17. Date(s) or Period	
8. Site Plan with North Arrow 		18. Style or Design ALTERED BEYOND RECOGNITION	
Coordinates Lat. 39° 31' N Long. 84° 24' W U.T.M. Reference 18Q 7229412 413749158		19. Architect or Engineer	
9. Name Easting Northing 7229412 413749158		20. Contractor or Builder	
10. Site <input checked="" type="checkbox"/> Building <input type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		21. Original Use, if apparent RESIDENTIAL	
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		22. Present Use AMERICAN LEGION HALL	
12. Is it Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/> MIDDLETOWN CIVIC ASSOC	
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		24. Owner's Name & Address, if known 101 N BOARD MIDDLETOWN, OHIO	
5. Name of Established District S. Main Street Historic District		25. Open to Public? AMERICAN LEGION MEMBERS AND PUBLIC Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
2. Further Description of Important Features STRUCTURE REDESIGNED, ALTERED, REMODELED TO ACCOMODATE LEGION HALL ACTIVITIES, PAINTED BRICK IN FRONT AND 1/3 OF NW SIDE BLDG, UNPAINTED BRICK OTHER 2/3 OF BLDG ONE STORY REMAINING WAS POSSIBLY 2 OR 3 STORIES ORIGINALLY. POSSIBLE INTRUSION 90'x140'x20' HIGH		26. Local Contact Person or Organization	
3. History and Significance ORIGINALLY HOME OF CAPT. ROBERT WILSON, AN EARLY PARTNER OF P.J. SOERG IN THE TOBACCO INDUSTRY, WAS ALSO PARTNER OF WILSON, MCCAULY TOBACCO CO. THIRD LARGEST IN COUNTRY AT THAT TIME		27. Other Surveys in Which Included	
4. Description of Environment and Outbuildings ASPHALT PARKING LOT TO SOUTH		28. No. of Stories	
5. Sources of Information FIELD SURVEY		29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		30. Foundation Material STONE	
		31. Wall Construction MASONRY	
		32. Roof Type & Material FLAT ASPHALT & GRAVEL	
		33. No. of Bays Front 5 Side	
		34. Wall Treatment PAINTED BRICK	
		35. Plan Shape RECTANGULAR	
		36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Moved <input type="checkbox"/>	
		37. Condition Interior FAIR Exterior FAIR	
		38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		39. Endangered? By What? ORIGINAL BLDG ALTERED BEYOND RECOGNITION Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		41. Distance from and Frontage on Road 60' FRONT PROP. FRONT 100'+ YARD	
		46. Prepared by LINDA VIENEKE	
		47. Organization CITY OF MIDDLETOWN	

BUT-55-8
BUTLER
MIDDLETOWN
AMERICAN LEGION MIDDLETOWN POST # 218
CAPT. ROBERT WILSON HOUSE



REVISED 8/76

7/29/75

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.
.
.
.
.
.
└	.	.	.	┌

42. (Cont'd)

43. (Cont'd)