

OHIO HISTORIC INVENTORY

Ohio Historic Preservation Officer
Ohio Historical Center
Columbus, Ohio 43211


CODED

No. **27 BUT. 68-8**
 County **BUTLER**
 Location of Negatives **CITY OF MIDDLETOWN**

4. Present Name(s) **314 S. MAIN STREET**
 5. Other Name(s) **JACOBY HOUSE**

Specific Location
**314 S. MAIN STREET WARD 2
 (LOT 858, PARCEL 47 AND 48)**

City or Town If Rural, Township & Vicinity
MIDDLETOWN, OHIO



Coordinates
 Lat **39° 31' N** Long. **84° 24' W**
 U.T.M. Reference
16 71227315 913766138

Easting Northing
 Site Building Structure Object

On National Register? Yes No
 Part of Estab. Yes No
 Hist. Dist.? Yes No

12. Is it Eligible? Yes No
 14. District Potent? Yes No

Name of Established District
S. Main Street Historic District

16. Thematic Category **C**
 17. Date(s) or Period **1887**
 18. Style or Design **QUEEN ANNE**
 19. Architect or Engineer
 20. Contractor or Builder
 21. Original Use, if apparent **RESIDENTIAL**
 22. Present Use **RESIDENTIAL**
 23. Ownership Public Private
 24. Owner's Name & Address, If known
**GRACE S. MILLER
 314 S. MAIN STREET
 MIDDLETOWN, OHIO**
 25. Open to Public? Yes No
 26. Local Contact Person or Organization
 27. Other Surveys in Which Included
NATIONAL REGISTER

28. No. of Stories **2**
 29. Basement? Yes No
 30. Foundation Material **STONE**
 31. Wall Construction **BRICK**
 32. Roof Type & Material **GABLE ASPHALT SHINGLE**
 33. No. of Bays Front Side
 34. Wall Treatment **STONE BRICK ARCHES TRIM**
 35. Plan Shape **RECTANGULAR**
 36. Changes (Explain in #42) Addition Altered Moved
 37. Condition Interior _____ Exterior **FAIR**
 38. Preservation Underway? Yes No
 39. Endangered? By What? Yes No
LACK OF MAINTENANCE
 40. Visible from Public Road? Yes No
 41. Distance from and Frontage on Road
PROP FRONT 50'±

Further Description of Important Features
SEVERAL ROUND ARCHED WINDOWS, PALLADIAN WINDOW, STONE LINTELS & SILLS ON ALL OTHER WINDOWS, BRICK CHIMNEY WITH PAINTED CLAY TILE STACKS

40' x 65' x 28' HIGH



History and Significance
BUILT BY CARRIE K. JACOBY IN 1887 - CAME FROM JACKSONBURG WAS LEADING INSURANCE BUSINESS TYCOON.

Description of Environment and Outbuildings
HEDGE LINED FRONT AND SIDE OF LOT, SHRUBBERY AND LAWN NEED MAINTENANCE AND TRIMMING.

Sources of Information
**FIELD SURVEY
 TITLE SEARCH 8/76**

46. Prepared by **LINDA WIENEKE**
 47. Organization **CITY OF MIDDLETOWN**
 48. Date **7/31/75** 49. Revision Date(s)

BUTLER 314 S. MAIN STREET

JACOBY HOUSE