

# OHIO HISTORIC INVENTORY

Ohio Historical Center  
Columbus, Ohio 43211

1. No. **32 BUT. 76.8**  
 2. County **BUTLER**  
 3. Location of Negatives  
**CITY OF MIDDLETOWN**  
 4. Present Name(s) **514 S. MAIN STREET** **CODED**  
 5. Other Name(s)  
**WILLIAM HANGER JOHNSON HOUSE**

6. Specific Location  
**514 S. MAIN STREET**  
**(LOT 888 PARCEL 20, WARD 2)**  
 7. City or Town If Rural, Township & Vicinity  
**MIDDLETOWN OHIO**  
 8. Site Plan with North Arrow

16. Thematic Category  
**D**  
 17. Date(s) or Period  
**1902**  
 18. Style or Design  
**SHINGLE/STICK STYLE**  
 19. Architect or Engineer  
  
 20. Contractor or Builder  
  
 21. Original Use, if apparent  
**RESIDENTIAL**  
 22. Present Use  
**RESIDENTIAL**  
 23. Ownership  
Public   
Private

28. No. of Stories **2**  
 29. Basement? Yes   
No   
 30. Foundation Material  
**STONE**  
 31. Wall Construction  
**FRAME**  
 32. Roof Type & Material  
**GABLE, ASPHALT SHINGLES**  
 33. No. of Bays  
Front **3** Side  
 34. Wall Treatment **WOOD**  
**WHITE PAINTED SIDING**  
 35. Plan Shape **IRREGULAR**  
 36. Changes Addition   
(Explain in #42) Altered   
Moved   
 37. Condition  
Interior  
Exterior **GOOD**

9. Coordinates  
 Lat. **39° 31' N** Long. **84° 24' W**  
 U.T.M. Reference

24. Owner's Name & Address, if known  
**OSCAR AND EVELYN DAY**  
**514 S. MAIN STREET**  
**MIDDLETOWN, OHIO**

38. Preservation Underway? Yes   
No   
 39. Endangered? By What? Yes   
No   
 40. Visible from Public Road? Yes   
No   
 41. Distance from and Frontage on Road  
**PROP. FRONT 50 ±**

10. Zone Easting Northing  
 11. On National Register? Yes   
No   
 12. Is it Eligible? Yes   
No   
 13. Part of Estab. Hist. Dist.? Yes   
No   
 14. District Potent'ial? Yes   
No   
 15. Name of Established District  
**S. Main Street Historic District**

25. Open to Public? Yes   
No   
 26. Local Contact Person or Organization  
  
 27. Other Surveys In Which Included  
**NATIONAL REGISTER**

42. Further Description of Important Features  
**FISHSCALE SHINGLES ON GABLE AND BAY WINDOW, STICK STYLE VERTICAL SIDING ON PORCH GABLE AS WELL AS DIAGONAL SUPPORTS,**  
**30' x 45' x 23' HIGH**



43. History and Significance  
  
 44. Description of Environment and Outbuildings  
**CONCRETE LAWN EDGING, TWO LARGE OAKS (RED IN FRONT, BLACK IN REAR) SAID TO BE OF THE LARGEST IN THIS AREA.**

45. Sources of Information  
**FIELD SURVEY**  
**RETURNED INVENTORY**  
**REVISED 8/76**

46. Prepared by  
**LINDA WIENEKE**  
 47. Organization  
**CITY OF MIDDLETOWN**  
 48. Date **8/31/75** 49. Revision Date(s)  
**S. W. HOWARD**

33 BUT. 76.8 BUTLER  
514 S. MAIN STREET  
W. H. JOHNSON HOUSE

51. Condition of Property

- |                                       |   |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent    | <input type="checkbox"/> Ruin             |
| <input type="checkbox"/> Good/Fair    | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____                                |

52. Historic Outbuildings and Dependencies

Barn Type(s)

---



---

- |  |                                       |                                 |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/>           | Smoke House <input type="checkbox"/>  | Privy <input type="checkbox"/>  |
| Summer Kitchen <input type="checkbox"/>              | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/>                        | Ice House <input type="checkbox"/>    |                                 |
| Designed landscape features <input type="checkbox"/> |                                       |                                 |

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

| Archaeological Feature: | Observed | Expected on Basis of<br>Archival Research |
|-------------------------|----------|---|
| Well                    | _____    | _____                                     |
| Privy                   | _____    | _____                                     |
| Cistern                 | _____    | _____                                     |
| Foundation              | _____    | _____                                     |
| Structural Rubble       | _____    | _____                                     |
| Formal Trash Dump       | _____    | _____                                     |
| Other _____             | _____    | _____                                     |

54. Farmstead Plan

|   |   |   |   |   |   |
|---|---|---|---|---|---|
| ┌ | . | . | . | . | └ |
| . | . | . | . | . | . |
| . | . | . | . | . | . |
| . | . | . | . | . | . |
| . | . | . | . | . | . |
| . | . | . | . | . | . |
| . | . | . | . | . | . |
| └ | . | . | . | . | └ |

42. (Cont'd)

43. (Cont'd)