


OHIO HISTORIC INVENTORY CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

1. No. 35 BUT. 79.8		4. Present Name(s) 604 S. MAIN		1. No. BUT 35.8
2. County KUTLER		5. Other Name(s) D.E. HARLAN HOUSE		
3. Location of Negatives CITY OF MIDDLETOWN				4. Present Name(s) 604 S. MAIN
6. Specific Location 604 S. MAIN STREET		16. Thematic Category C		
7. City or Town If Rural, Township & Vicinity MIDDLETOWN, OHIO		17. Date(s) or Period 1890's		29. Basement? Yes <input type="checkbox"/> No <input type="checkbox"/>
8. Site Plan with North Arrow		18. Style or Design SHINGLE STYLE		
		19. Architect or Engineer		31. Wall Construction FRAME
9. Coordinates Lat. 39°31'N Long. 84°24'W U.T.M. Reference 11G 724546 437163411		20. Contractor or Builder		
Zone Easting Northing		21. Original Use, if apparent RESIDENTIAL		33. No. of Bays Front 3 Side 4
10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/>		22. Present Use 2 FAMILY RESIDENTIAL		
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23. Ownership Public <input type="checkbox"/> Private <input type="checkbox"/>		35. Plan Shape IRREGULAR
12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>		24. Owner's Name & Address, if known HEBE ECKEN 64 S. MAIN ST. MIDDLETOWN, OHIO, 45042		
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input type="checkbox"/>		25. Open to Public? Yes <input type="checkbox"/> No <input type="checkbox"/>		37. Condition Interior _____ Exterior VERY GOOD
14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		26. Local Contact Person or Organization		
15. Name of Established District S. Main Street Historic District		27. Other Surveys in Which Included NATIONAL REGISTER		39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
42. Further Description of Important Features HUGE HOUSE DIVIDED INTO A 2 FAMILY APARTMENT. SEVERAL ARCHED LEADED GLASS WINDOWS, 3 LARGE BRICK CHIMNEYS, FISH SCALE SHINGLES ALL AROUND ENTIRE HOUSE.		40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>		
43. History and Significance		46. Prepared by LINDA WIENEKE		5. Other Name(s) D.E. HARLAN HOUSE
44. Description of Environment and Outbuildings		47. Organization CITY OF MIDDLETOWN		
45. Sources of Information FIELD SURVEY 9/76		48. Date 9/76		49. Revision Date(s)
		49. Revision Date(s)		



51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.
.
.
.
.
.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)