

CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

OHIO HISTORIC INVENTORY

1. No. 49 BUT. 87.8		4. Present Name(s) 603 S. MAIN STREET	
2. County BUTLER		5. Other Name(s)	
3. Location of Negatives CITY OF MIDDLETOWN			
6. Specific Location 603 S. MAIN STREET		16. Thematic Category D	28. No. of Stories 3
7. City or Town If Rural, Township & Vicinity MIDDLETOWN OHIO		17. Date(s) or Period 1900's	29. Basement? Yes <input type="checkbox"/> No <input type="checkbox"/>
8. Site Plan with North Arrow 6TH AVE.		18. Style or Design	30. Foundation Material BRICK
		19. Architect or Engineer	31. Wall Construction FRAME
		20. Contractor or Builder	32. Roof Type & Material SHINGLE - ASPHALT SHINGLE
9. Coordinates Lat. 39°31'N Long. 84°24'W U.T.M. Reference 11U 7225914 4374631411		21. Original Use, if apparent RESIDENTIAL	33. No. of Bays Front 3 Side 3
10. Zone Easting Northing Site <input type="checkbox"/> Building <input checked="" type="checkbox"/> Structure <input type="checkbox"/> Object <input type="checkbox"/>		22. Present Use RESIDENTIAL - MULTI-FAMILY	34. Wall Treatment WOOD SHINGLES
11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/>	23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/>	35. Plan Shape RECTANGULAR
13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input type="checkbox"/>	14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	24. Owner's Name & Address, if known LEE & REGINA KENNEDY	36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/>
15. Name of Established District S. Main Street Historic District		25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	37. Condition Interior _____ Exterior FAIR
42. Further Description of Important Features ROUGH AND TORNADOED OF BRICK WITH WOOD SIDING ON FIRST FLOOR AND WOOD SHINGLES ON SECOND CORNICE BRACKETS - FIRST AND SECOND FLOORS, LARGE 2 CABBLED DORMER		26. Local Contact Person or Organization	38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
43. History and Significance		27. Other Surveys in Which Included NATIONAL REGISTER	39. Endangered? By What? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NEEDS REPAIR
44. Description of Environment and Outbuildings			
45. Sources of Information FIELD SURVEY - 11/76			
46. Prepared by LINDA WIENCKE		47. Organization CITY OF MIDDLETOWN	
48. Date 11/76		49. Revision Date(s)	

1. No. **49**
2. County **BUTLER**
4. Present Name(s) **603 S. MAIN**
5. Other Name(s)

51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.
.
.
.
.
.
└	.	.	.	┌

42. (Cont'd)

43. (Cont'd)