

OHIO HISTORIC INVENTORY CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

No. BUT-95-8 51
County BUTLER
Location of Negatives
CITY OF MIDDLETOWN

4. Present Name(s)
503 S. MAIN STREET
5. Other Name(s)

Specific Location
503 S. MAIN STREET
(LOT 808, PARCEL 2, WARD 2)


16. Thematic Category
C
17. Date(s) or Period
1891

28. No. of Stories 2
29. Basement? Yes No

City or Town If Rural, Township & Vicinity
MIDDLETOWN, OHIO

18. Style or Design
QUEEN ANNE

30. Foundation Material
STONE



19. Architect or Engineer

31. Wall Construction
BRICK

20. Contractor or Builder

32. Roof Type & Material
GABLE ASPHALT SHINGLE

21. Original Use, if apparent
RESIDENTIAL

33. No. of Bays
Front 3 Side

22. Present Use
RESIDENTIAL

34. Wall Treatment
WHITE PAINT ON BRICK

23. Ownership Public Private

35. Plan Shape IRREGULAR

Coordinates
Lat 39° 31' N Long. 84° 24' W
U.T.M. Reference

24. Owner's Name & Address, if known
KENNETH BILLMAN
503 S. MAIN STREET
MIDDLETOWN, OHIO

36. Changes (Explain in #42) Addition Altered Moved
37. Condition Interior EXCELLENT Exterior VERY GOOD

69	72	76	66	73	76	43	7
Easting				Northing			
Site <input type="checkbox"/>				Structure <input type="checkbox"/>			
Building <input type="checkbox"/>				Object <input type="checkbox"/>			

25. Open to Public? Yes No

38. Preservation Underway? Yes No

10. On National Register? Yes No

26. Local Contact Person or Organization

39. Endangered? By What? Yes No

11. Part of Estab. Yes Hist. Dist.? No

27. Other Surveys In Which Included
NATIONAL REGISTER

40. Visible from Public Road? Yes No

Name of Established District
S. Main Street Historic District

41. Distance from and Frontage on Road
PROP FRONT 50±

Further Description of Important Features
PAINTED BRICK HOUSE WITH RUSTICATED STONE LINTELS, WOOD SHINGLE DETAIL IN GABLES, PAINTED BRICK CHIMNEY, ALL ORIGINAL INTERIOR WOODWORK RESTORED TO ORIGINAL CONDITION.
30 x 55' x 25' HIGH



History and Significance

Description of Environment and Outbuildings
GARAGE-CARPORAT AT REAR-BRICK, BRICK WALL DOWN CENTER OF BACKYARD. CONCRETE LAWN EDGING.

Sources of Information
FIELD SURVEY

46. Prepared by
LINDA WIENEKE

REVISID 8/16

47. Organization
CITY OF MIDDLETOWN

8/1/75

48. Date 1/9/81 (High District)

BUT-95-8 BUTLER 503 S MAIN STREET

51. Condition of Property

- Excellent
- Good/Fair
- Deteriorated
- Ruin
- Destroyed/Burned
- Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed
- Summer Kitchen
- Silo
- Designed landscape features
- Smoke House
- Spring House
- Ice House
- Privy
- Garage

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.
.
.
.
.
.
└	.	.	.	└

42. (Cont'd)

43. (Cont'd)