



OHIO HISTORIC INVENTORY CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 55 BUT. 99.8</p> <p>2. County BUTLER</p> <p>3. Location of Negatives CITY OF MIDDLETOWN</p>	<p>4. Present Name(s) 313 S. MAIN STREET</p> <p>5. Other Name(s)</p>	
<p>6. Specific Location 313 S. MAIN STREET (LOT 1087, PARCEL 12, WARD 2)</p> <p>7. City or Town If Rural, Township & Vicinity MIDDLETOWN, OHIO</p> <p>8. Site Plan with North Arrow  </p> <p>9. Coordinates Lat. 39° 31' N Long. 84° 24' W U.T.M. Reference 11U 722779 4376618</p> <p>Zone Easting Northing 10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>15. Name of Established District S. Main Street Historic District</p>	<p>16. Thematic Category C</p> <p>17. Date(s) or Period 1890</p> <p>18. Style or Design QUEEN ANNE</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent RESIDENTIAL</p> <p>22. Present Use RESIDENTIAL</p> <p>23. Ownership Public <input type="checkbox"/> Private <input type="checkbox"/></p> <p>24. Owner's Name & Address, if known DALE AND CHERYL MARTLAGE 311-313 S. MAIN MIDDLETOWN, OHIO</p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization</p> <p>27. Other Surveys in Which Included NATIONAL REGISTER</p>	<p>28. No. of Stories 2</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction BRICK</p> <p>32. Roof Type & Material COBBLES ASPHALT SHINGLES</p> <p>33. No. of Bays Front 2 Side</p> <p>34. Wall Treatment WHITE ALUMINUM SIDING</p> <p>35. Plan Shape IRREGULAR</p> <p>36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input checked="" type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior Exterior FAIR</p> <p>38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road PROP. FRONT 50' ±</p>
<p>42. Further Description of Important Features ROOMS ADDED IN REAR OF STRUCTURE, HOUSE ALTERED TO MULTIFAMILY MAJOR INTERIOR STAIRWAY REMOVED, ALUMINUM SIDING ADDED, PALLADIAN MOTIF WINDOW, LEAVE BRACKETS, FRONT DOOR BEING REFINISHED.</p> <p style="text-align: right;">30' x 80' x 28' HIGH</p>		
<p>43. History and Significance</p>		
<p>44. Description of Environment and Outbuildings</p>		
<p>45. Sources of Information FIELD SURVEY INTERVIEW WITH DALE MARTLAGE</p>	<p>46. Prepared by LINDA WIENEKE</p> <p>47. Organization CITY OF MIDDLETOWN</p> <p>48. Date 7/17 49. Revision Date(s)</p>	

REVISED 8/16

1. No. **55**
 2. County **BUTLER**
 4. Present Name(s) **313 S. MAIN STREET**
 5. Other Name(s)

51. Condition of Property

- Excellent
- Good/Fair
- Deteriorated
- Ruin
- Destroyed/Burned
- Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed
- Summer Kitchen
- Silo
- Designed landscape features
- Smoke House
- Spring House
- Ice House
- Privy
- Garage

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of			
		Archival Research			

- | | | | | | |
|-------------------|-------|-------|--|--|--|
| Well | _____ | _____ | | | |
| Privy | _____ | _____ | | | |
| Cistern | _____ | _____ | | | |
| Foundation | _____ | _____ | | | |
| Structural Rubble | _____ | _____ | | | |
| Formal Trash Dump | _____ | _____ | | | |
| Other _____ | _____ | _____ | | | |

54. Farmstead Plan

42. (Cont'd)

43. (Cont'd)