


OHIO HISTORIC INVENTORY

CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 57 BUT. 103 .8</p> <p>2. County BUTLER</p> <p>3. Location of Negatives CITY OF MIDDLETOWN</p>	<p>4. Present Name(s) 231 S. MAIN STREET</p> <p>5. Other Name(s) WAMPLER DENNY HOUSE</p>							
<p>8. Specific Location 231 S. MAIN STREET (LOT 1091, PARCEL G, WARD 2)</p> <p>7. City or Town If Rural, Township & Vicinity MIDDLETOWN OHIO</p> <p>8. Site Plan with North Arrow</p> 	<p>16. Thematic Category D</p> <p>17. Date(s) or Period</p> <p>18. Style or Design NON-DESCRIPT</p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent RESIDENTIAL</p> <p>22. Present Use RESIDENTIAL</p> <p>23. Ownership Public <input type="checkbox"/> Private <input type="checkbox"/></p> <p>24. Owner's Name & Address, if known MARY M. PFISTER</p>	<p>26. No. of Stories 2</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction FRAME</p> <p>32. Roof Type & Material GALE. ASPHALT SHINGLE</p> <p>33. No. of Bays Front 3 Side 3</p> <p>34. Wall Treatment WOOD BEIGE. PAINTED SIDING</p> <p>35. Plan Shape RECTANGULAR</p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior _____ Exterior FAIR</p> <p>38. Preservation Underway? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road PROP. FRONT 90±</p>						
<p>9. Coordinates Lat. 39° 31' N Long. 84° 24' W U.T.M. Reference 11U 7H 278131 43767211</p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:33%;">Zone</td> <td style="width:33%;">Easting</td> <td style="width:33%;">Northing</td> </tr> <tr> <td>10. Site Building <input checked="" type="checkbox"/></td> <td>Structure Object <input type="checkbox"/></td> <td></td> </tr> </table> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>15. Name of Established District S. Main Street Historic District</p>	Zone	Easting	Northing	10. Site Building <input checked="" type="checkbox"/>	Structure Object <input type="checkbox"/>		<p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization</p> <p>27. Other Surveys in Which Included NATIONAL REGISTER</p>	<p>42. Further Description of Important Features BEIGE PAINTED SIDING, WITH BEIGE PAINTED WINDOW FRAME, BROWN WINDOW SCREENS, BEIGE COVERED PORCH (BROWN) POSTS (DETAILED) GREEN CANVAS CANOPY ON FRONT PORCH; WOOD FLOOR TO PORCH BRICK CHIMNEYS CARPORT ADDITION 25'x70'x23' HIGH</p>
Zone	Easting	Northing						
10. Site Building <input checked="" type="checkbox"/>	Structure Object <input type="checkbox"/>							
<p>43. History and Significance HOME OF LEADING INDUSTRIALIST AND BUSINESSMAN OF MIDDLETOWN</p>	<p>44. Description of Environment and Outbuildings CARPORT NOT COMPATIBLE, WELL SHADED LOT,</p>							
<p>45. Sources of Information FIELD SURVEY</p> <p style="text-align: right;">REVISED 8/76</p>	<p>46. Prepared by LINDA WIENEKE</p> <p>47. Organization CITY OF MIDDLETOWN</p> <p>48. Date 49. Revision Date(s)</p>							

1. No. **BUT. 58.8**
 2. County **BUTLER**
 4. Present Name(s) **231 S. MAIN ST**
 5. Other Name(s)



51. Condition of Property

- | | |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Ruin |
| <input type="checkbox"/> Good/Fair | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____ |

52. Historic Outbuildings and Dependencies

Barn Type(s)

- | | | |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/> | Smoke House <input type="checkbox"/> | Privy <input type="checkbox"/> |
| Summer Kitchen <input type="checkbox"/> | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/> | Ice House <input type="checkbox"/> | |
| Designed landscape features <input type="checkbox"/> | | |

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	└
.
.
.
.
.
.
└	└

42. (Cont'd)

43. (Cont'd)