

CODED

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

OHIO HISTORIC INVENTORY

1. No. 64 BUT-108-8 4. Present Name(s) 224 YANKEE ROAD

2. County BUTLER 5. Other Name(s)

3. Location of Negatives
CITY OF MIDDLETOWN

6. Specific Location
224 YANKEE ROAD
(LOT 1074, PARCEL 18, WARD 2)

16. Thematic Category

17. Date(s) or Period


28. No. of Stories 2

29. Basement? Yes No

7. City or Town If Rural, Township & Vicinity
MIDDLETOWN, OHIO

18. Style or Design
VICTORIAN INFLUENCES

8. Site Plan with North Arrow



19. Architect or Engineer

20. Contractor or Builder

21. Original Use, if apparent
RESIDENTIAL

22. Present Use
RESIDENTIAL

23. Ownership Public Private

24. Owner's Name & Address, if known
VIOLA MORNINGSTAR
224 YANKEE ROAD
MIDDLETOWN, OHIO

30. Foundation Material
BRICK

31. Wall Construction
FRAME

32. Roof Type & Material
CABLE ASPHALT SHING

33. No. of Bays Front 3 Side

34. Wall Treatment
WOOD SIDING

35. Plan Shape RECTANGLE

36. Changes (Explain in #42) Addition Altered Moved

37. Condition Interior _____ Exterior GOOD

9. Coordinates
Lat. 39° 31' N Long. 84° 24'
U.T.M. Reference
11U 72281819 4376736

10. Zone Easting Northing

11. On National Register? Yes No 12. Is It Eligible? Yes No

13. Part of Estab. Hist. Dist.? Yes No 14. District Potent? Yes No

15. Name of Established District
SOUTH MAIN ST. HISTORIC DISTRICT

25. Open to Public? Yes No

26. Local Contact Person or Organization

27. Other Surveys in Which Included
NATIONAL REGISTER

38. Preservation Underway? Yes No


39. Endangered? By What? Yes No NEEDS PAINT

40. Visible from Public Road? Yes No

41. Distance from and Frontage on Road
PROP FRONT 80'

42. Further Description of Important Features
SLIGHT PITCHED ROOF, RELATIVELY LITTLE TRIM-
WOOD WINDOW FRAMES, IONIC PORCH COLUMNS

30' x 40' x 23' HIGH



43. History and Significance

44. Description of Environment and Outbuildings
OUTBUILDINGS IN REAR-WOOD SIDING FRAME CONSTRUCTION
SEVERAL TREES, SHRUBS.

45. Sources of information
FIELD SURVEY

46. Prepared by
LINDA WIENEKE

47. Organization
CITY OF MIDDLETOWN

48. Date | 49. Revision Date(s)

REVISED 8/76

1. No. BUT-108-8
2. County BUTLER
4. Present Name(s) 224 YANKEE ROAD
5. Other Name(s)

51. Condition of Property

- Excellent Ruin
 Good/Fair Destroyed/Burned
 Deteriorated Date _____

52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed Smoke House Privy
 Summer Kitchen Spring House Garage
 Silo Ice House
 Designed landscape features

53. Affiliated OAI Site Number(s) _____ one _____ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	└
.
.
.
.
.
.
.
└	┌

42. (Cont'd)

43. (Cont'd)