



# OHIO HISTORIC INVENTORY

Ohio Historical Center  
Columbus, Ohio 43211

<p>1. No. <b>68 BUT-112-8</b></p> <p>2. County <b>BUTLER</b></p> <p>3. Location of Negatives <b>CITY OF MIDDLETOWN</b></p>	<p>4. Present Name(s) <b>1000 SECOND AVE.</b></p> <p>5. Other Name(s)</p>	CODED	1. No. <b>BUT-112-8</b>						
<p>6. Specific Location <b>1000 SECOND AVE. (LOT # 65 PARCELS)</b></p>	<p>16. Thematic Category</p> <p>17. Date(s) or Period</p>	<p>28. No. of Stories <b>2</b></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <b>BRICK - GELCK</b></p> <p>31. Wall Construction <b>FRAME</b></p> <p>32. Roof Type &amp; Material</p>	2. County <b>BUTLER</b>						
<p>7. City or Town If Rural, Township &amp; Vicinity <b>HIDDLETOWN, OHIO</b></p> <p>8. Site Plan with North Arrow <b>SECOND AVE.</b></p> 	<p>18. Style or Design <b>NON-DESCRIPT</b></p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent <b>RESIDENCE</b></p> <p>22. Present Use <b>RESIDENCE</b></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name &amp; Address, if known <b>MARGARET CLAPP 1 SIERRA MIDDLETOWN, OHIO</b></p>	<p>33. No. of Bays Front Side</p> <p>34. Wall Treatment <b>PAINTED</b></p> <p>35. Plan Shape <b>RECT.</b></p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <b>GOOD</b> Exterior <b>GOOD</b></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road</p>	4. Present Name(s) <b>SECOND AVE.</b>						
<p>9. Coordinates Lat. <b>39° 31' N</b> Long. <b>84° 21' W</b> U.T.M. Reference <b>116 722946 413768 219</b></p> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:25%;">Zone</td> <td style="width:25%;">Easting</td> <td style="width:25%;">Northing</td> </tr> <tr> <td>10. Site Building <input checked="" type="checkbox"/></td> <td>Structure Object <input type="checkbox"/></td> <td></td> </tr> </table> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>15. Name of Established District</p>	Zone	Easting	Northing	10. Site Building <input checked="" type="checkbox"/>	Structure Object <input type="checkbox"/>		<p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization <b>MARGARET CLAPP</b></p> <p>27. Other Surveys in Which Included</p>	<p>42. Further Description of Important Features <b>DETAILED WOOD BATHEN BOARDS AT CORNERS - EXCELLENT WOOD DETAILS ON PORCH AND PORCH SUPPORTING MEMBERS</b></p>	5. Other Name(s)
Zone	Easting	Northing							
10. Site Building <input checked="" type="checkbox"/>	Structure Object <input type="checkbox"/>								
<p>43. History and Significance</p>									
<p>44. Description of Environment and Outbuildings <b>TRAFFIC EXHD W ON 2ND AVE.</b></p>									
<p>45. Sources of Information <b>FIELD SURVEY</b></p>	<p>46. Prepared by</p> <p>47. Organization <b>CITY OF MIDDLETOWN</b></p> <p>48. Date   49. Revision Date(s)</p>								

51. Condition of Property

- |                                       |   |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent    | <input type="checkbox"/> Ruin             |
| <input type="checkbox"/> Good/Fair    | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____                                |

52. Historic Outbuildings and Dependencies

Barn Type(s)

---



---

- |  |                                       |                                 |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/>           | Smoke House <input type="checkbox"/>  | Privy <input type="checkbox"/>  |
| Summer Kitchen <input type="checkbox"/>              | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/>                        | Ice House <input type="checkbox"/>    |                                 |
| Designed landscape features <input type="checkbox"/> |                                       |                                 |

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	└
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
└	.	.	.	┌

42. (Cont'd)

43. (Cont'd)