



# OHIO HISTORIC INVENTORY CODED

Ohio Historic Preservation Office  
Ohio Historical Center  
Columbus, Ohio 43211

<p>1. No. <u>79 BUT. 123.8</u></p> <p>2. County <u>BUTLER</u></p> <p>3. Location of Negatives <u>CITY OF MIDDLETOWN</u></p>	<p>4. Present Name(s) <u>1008 FIRST AVE.</u></p> <p>5. Other Name(s)</p>	
<p>6. Specific Location <u>1008 FIRST AVE. (LOT PT. 60 PARCEL 26)</u></p> <p>7. City or Town If Rural, Township &amp; Vicinity <u>MIDDLETOWN, OHIO</u></p> <p>8. Site Plan with North Arrow <u>FIRST AVE.</u></p> 	<p>16. Thematic Category</p> <p>17. Date(s) or Period</p> <p>18. Style or Design <u>NON-DESCRIPT</u></p> <p>19. Architect or Engineer</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent <u>RESIDENTIAL</u></p> <p>22. Present Use <u>RESIDENTIAL</u></p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name &amp; Address, if known <u>MARION B. HENRY 103 S. MAIN ST. MIDDLETOWN</u></p> <p>25. Open to Public? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>26. Local Contact Person or Organization</p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories <u>2</u></p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material <u>BRICK &amp; CONCRETE</u></p> <p>31. Wall Construction <u>FRAME</u></p> <p>32. Roof Type &amp; Material <u>SHINGLE GABLE</u></p> <p>33. No. of Bays Front Side</p> <p>34. Wall Treatment <u>ASPHALT SHINGLE</u></p> <p>35. Plan Shape <u>RECTANGLE</u></p> <p>36. Changes (Explain in #42) Addition <input type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior <u>GOOD</u> Exterior <u>GOOD</u></p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road</p>
<p>9. Coordinates Lat. <u>39° 31' N</u> Long. <u>84° 34' W</u> U.T.M. Reference <u>11G 7230133 43769160</u></p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input type="checkbox"/></p> <p>14. District Potent'l? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>15. Name of Established District</p>	<p>42. Further Description of Important Features</p>	<p>4. Present Name(s) <u>1008 FIRST AVE.</u></p> <p>5. Other Name(s)</p> 
<p>43. History and Significance</p>	<p>44. Description of Environment and Outbuildings</p>	
<p>45. Sources of Information <u>FIELD SURVEY</u></p>	<p>46. Prepared by</p> <p>47. Organization <u>CITY OF MIDDLETOWN</u></p> <p>48. Date   49. Revision Date(s)</p>	

1. No. BUT. 123.8

2. County BUTLER

4. Present Name(s) 1008

5. Other Name(s) FIRST AVE.

5. Other Name(s)

51. Condition of Property

- |                                       |   |
|---------------------------------------|---|
| <input type="checkbox"/> Excellent    | <input type="checkbox"/> Ruin             |
| <input type="checkbox"/> Good/Fair    | <input type="checkbox"/> Destroyed/Burned |
| <input type="checkbox"/> Deteriorated | Date _____                                |

52. Historic Outbuildings and Dependencies

Barn Type(s)

---



---

- |  |                                       |                                 |
|--|---------------------------------------|---------------------------------|
| Corn Crib or Shed <input type="checkbox"/>           | Smoke House <input type="checkbox"/>  | Privy <input type="checkbox"/>  |
| Summer Kitchen <input type="checkbox"/>              | Spring House <input type="checkbox"/> | Garage <input type="checkbox"/> |
| Silo <input type="checkbox"/>                        | Ice House <input type="checkbox"/>    |                                 |
| Designed landscape features <input type="checkbox"/> |                                       |                                 |

53. Affiliated OAI Site Number(s) \_\_\_\_\_ one \_\_\_\_\_ multiple

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

54. Farmstead Plan

┌	.	.	.	┐
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
.	.	.	.	.
└	.	.	.	┘

42. (Cont'd)

43. (Cont'd)